

2001 Thomas Bookmobile

Sale Price: \$25,000 or best offer

Size – 32 feet Weight – 14,000 pounds Mileage – 113,647 Hours – 8,000

Summary of Factors Affecting Current Condition

- 1. Generator nonfunctional.
- 2. Hydraulic step for staff and patron access nonfunctional and no longer attached. Sufficient frame to secure steps no longer available due to deterioration.
- 3. Electrolysis due to contact of non-alike metals evident on body. Possibly affecting condition of frame. Body is aluminum and frame and miscellaneous parts are steel.
- 4. Several batteries no longer hold a charge.
- 5. Frame bent making access to battery and generator slide out compartments questionable.
- 6. Roof leaks due to deteriorated gaskets between riveted seams.
- 7. Engine coolant tank.
- 8. Auxiliary heating and cooling systems subject to frequent costly breakdowns. (heating currently not working.)

For further information contact:

Joanne Eldridge, Library Director 440-244-1192, ext. 227 jeldridge@lpls.info